

Burning tar at our Black Smiths Day 2004.



The barrel is filled with pine wood, rich of resin.



I,m fetching some clay.



I use the clay and sand to tighten around the barrel.



Some wood is stacked around and on top of the barrel. Now it's ready to start the fire



Here is the pipe where it will drop out about 5 liters
Tar of good quality.



After half an hour the first drop will show up.



After another 2 or 3 hours it's all over and we have our 5 liters of good tar.



Britt and I looks rather satisfied with the result of the Black Smiths Day 2004.